

S134 - High Temperature Additive

Description:

Special clearcoat additive for hot and humid conditions.

Suitable Substrates:

Hydrobase

Mixing Ratio: Add 5% to clearcoat before addition of hardener.

Raw Material: Silicone oil solution

Important Remarks:

- For professional use only.
- Only use S134 over Hydrobase in hot and humid conditions.

• Do not exceed the recommended dosage.

Cleaning of equipment: Clean after use with Hymax Cleaning thinner.



Wear suitable protection

SDS: See the safety data sheet

The Warnings displayed on the product labels should be followed.

The information contained here represents the current state of our knowledge and is intended as a guide to our products and their uses.