

WS35 - Blending Additive

Description:

- For Blending-in Hydrobase Waterbourne Basecoat.
- Easy handling.
- Ready to spray.

Application 1:

Blending-in Hydrobase Basecoat directly over WS35 Blending agent.



- Mix WS35 5:1 with Hydrobase water WS20.
- Spray blending area with one coat of WS35 avoiding the edges
- Apply mixed Hydrobase Basecoat in the wet film until covered.
- Blend-in the overlapping area with reduced air pressure (1.0-1.5 bar)





Hymax Clearcoats.

Application 2:

Blending-in Hydrobase Basecoat mixed with WS135 Blending agent.





- Mix Hydrobase Basecoat with 50% WS35 blending agent.



Hymax Clearcoats.



WS35 - Blending Additive

Note:

Occasionally it may be necessary to obtain opacity on the primed area before

proceeding.

Cleaning the **Equipment:**

Clean after use with Water.

Safety:

Refer to Material Safety Data Sheet (MSDS) for complete safety instructions. The technical data sheet listed has been compiled in good faith for your convenience and guidance. No warranty, expressed or implied, is intended or given by the information on this sheet.

Note: General recommends that our products not be used under 10°C. Usage below 10°C can result in extended drying times or product failure.

Product Da